



Notes:

1. This drawing is the property of ACP (Concrete) Ltd and is not to be copied in any way without prior written approval from AXP (Concrete) Ltd.
2. Brackets A to be clipped to steel work using M12 bolts into cast in sockets. 4 No Brackets per panel (1 in each corner).
3. Fixing Angles have two fixing scenarios:
 - a. Fix to prestressed concrete panels using M12 excalibar bolts or equivalent to the manufacturers specification.
 - b. Fix to steel column/beams using M12 bolts c/w nut & washer.

It is the responsibility of the main contractor to notify ACP(Concrete)Ltd of any subsequent revisions which may affect this design.

Rev.	Checked By	Dwn	Date


ACP (Concrete) Ltd
 Wood Lane Business Centre
 Wood Lane
 Uttoxeter
 Staffs
 ST14 8JR
 Tel:01889 598660 Fax:01889 568160

Job Title:
 TYPICAL FIXING ARRANGEMENT
 TO FACE OF COLUMNS & INSIDE
 COLUMN WEBS
 Drawn: TAW Scale: N.T.S Date: 20/05/08
 Drawing No. 2001